



No.	Part No.	RoHS	SAP	Part Name	Specifications	Qty	Remarks	Wiring diagram symbol
1	001-1015		230709	Safety release packet	2.5 bar	1		
2	1-1030		246217	Plate heat exchanger CB460-504-F		1		
3	001-10052		273610	Circulation pump		1		
4	1-1028		282953	Manometer	50-4 0-4 bar 1/8"	1		
5	1-1041		221100	Expansion Vessel <G>		1	12 L	
6	1-4016		219781	Diverting valve <G>		1		
7	1-5126			Filter	DN25	1		
8	17-0058		247065	Immersion heater	6, 9 kW / 1, 3-phase, comp	1		

The Spare Parts Database is maintained with great care. Nonetheless, errors cannot be completely ruled out. If you notice an error, please let us know. We reserve the right to make technical changes.

Mitsubishi Electric Spare Parts



9	1-6215		219782	Immers heater 6+3kw (FRA)<233905>		1	
10	19-6010		229795	Seal to heater <G>		1	
11	1-8004		219783	Chain anode <G>		1	
12	1-4018	G	230714	Inset diverting valve	22 mm	1	
13	1-1020		246467	Flow switch		1	
14	001-9207		246468	Display	Complete with clips	1	
15	001-9322		239766	Hose packet diverting valve tank		1	
16	001-9323		239767	Hose packet safety release packag		1	
17	001-9324		239768	Hose packet immersion heater tank		1	
18	1-1009		239769	Automatic air vent		1	
19	1-5248			Manual air vent		1	
20	16-9427		239771	Copper pipe filter		1	Circulation pump
21	16-9428		239772	Copper pipe		1	Immersion heater & heat exchanger
22	16-9429		239773	Copper pipe		1	Tank radiator
23	16-9430		239774	Copper pipe		1	Diverting valve radiator
24	16-9431			Copper pipe	5/8"	1	
25	16-9432		239775	Copper pipe 3/8"		1	
26	105-2003			Copper pipe	Length 220 mm	1	
27	18-6022		239776	Top panel		1	
28	18-96070		239777	Front panel		1	
29	18-6114		239778	Side panel		1	
30	18-6153		239779	Back panel		1	

The Spare Parts Database is maintained with great care. Nonetheless, errors cannot be completely ruled out. If you notice an error, please let us know. We reserve the right to make technical changes.